





Габаритный чертеж					Справ. №		Перв. примен.	
Изм. № подл.	Подп. и дата	Взам. инв. №	Инв. № дубл.	Подп. и дата				

Technical drawing of a component, likely a flange or a similar mechanical part. The drawing shows a cross-section of the part. Two dimensions are indicated: S11, which is the thickness of the flange, and S13, which is the thickness of the main body of the part. The drawing is oriented vertically, with the dimensions S11 and S13 labeled along the vertical axis.



1 Допускается устанавливать кронштейн в обратной ориентации.

					Габаритный чертеж				
					Зонды ДВ2ТС(М)-5Т-5П-АК	Лит.	Масса	Масштаб	
Изм.	Лист	№ докум.	Подп.	Дата				1:1	
Разраб.	Перелыгин								
Пров.									
Т.контр.						Лист	Листов	1	
Нач.отд.						ООО НПК "МИКРОФОР"			
Н.контр.									
Утв.									